

LDWSF  
4.001  
2/27/14

## Sanga, Ravi

**From:** Dyer, Miles [mdyer@JorgensenForge.com]  
**Sent:** Thursday, February 27, 2014 10:27 AM  
**To:** Ernst, William D; Dee Gardner; Sanga, Ravi; 'Amy Essig Desai'; Philip Spadaro; Bob Romagnoli; Bradley M. Marten; Brian K. Ferrasci-O'Malley; Christopher Schraff (cschraff@porterwright.com); Jeff B. Kray  
**Subject:** Completed Coffor Dam Project  
**Attachments:** Front View Completed Coffor Dam.jpg; Side view completed coffor dam.jpg; 13150-S1-1-OPT1-ALT-021914-ASBLT.PDF; Closer View RipRap inside Coffor Dam, Upland Side.jpg; Peering inside Coffor Dam from Top of Bank.jpg; Front View Completed Coffor Dam.jpg; Side view completed coffor dam.jpg; Coffor Dam Exterior View.jpg

The LDW in-water coffer dam installation located adjacent to JFC and Boeing's property lines was completed on 26 February, 2014.


Pictures of the completed coffer dam are attached. The coffer dam topped off at +15 feet. PP&M has full access into the coffer dam for the dredging work scheduled later this year. The barge and control cabin rest approximately 15 feet above the height of the sheet wall sides, providing clear visibility into the dredging area.

Axis Survey attachment (13150-S1-1OPT1ALT) identifies the footprint of the template on the B&T base map. This footprint was a perfect match.

During sheet steel panel installation, PP&M did not encounter any obstructions.

Navigation safety lights were placed on the two in-water corners of the coffer dam per USCG's request.

Miles Dyer  
Director, Environmental Programs



Jorgensen Forge Corporation  
8531 East Marginal Way South  
Seattle, Washington 98108  
Office Ph#: (206) 965-1352  
Mobile: (740) 777-7808  
Fax: (206) 357-1071  
[mdyer@jorgensenforge.com](mailto:mdyer@jorgensenforge.com)

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

This Email message contained an attachment named image001.jpg which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*











